

# FRAX NEWS – Improved cables and clamps

---

The new innovative FRAX clamp helps the user to connect and achieve repeatable test results in the simplest way possible. It handles both round and flat connectors and is easy to attach to any bushing. The firm grip allows heavy cables and accessories to be mounted near the bushing without any risk of the clamp falling off. The new clamp offers all necessary connectors (BNC, braid, ground, cable strain relief) in one clamp. Simply the best...



# FRAX-101 Cable Set

---


This cable set comes as standard with all FRAX-101 and it consists of:

- 1 pcs single coaxial cable for Measure (black), 18 m (60 ft)
- 1 pce orange twin coax cable for Generator & Reference (Yellow & Red), 18 m (60ft)
- 9 m (30 ft) available as an optional accessory
- 4 pcs ground braids, 3 m (10 ft)
- 2 pcs ground braid connector 0,3 m (1 ft)
- 1 pce ground cable for the FRAX unit, 5 m (15 ft)



# FRAX – Bushing connection

---



Cable strain relief

Coaxial cable from FRAX  
- Generator (Yellow)  
- Reference (Red)

Ground braid connected to ground. Keep the braid straight along the bushing and ground the braid at the base of the bushing. Ensure good connection.

# FRAX – Cable setup

---

The ground braid shall go from the top clamp the shortest way to the bottom of the bushing. Good ground connection is essential.

Using an easy repeatable cable setup is crucial to ensure reliable FRA results.

